

CONFINED SPACES SURVEY

Original Survey 11/96; Updated 8/2000, 7/02, 3/03, 8/03, 9/07, 3/09											
BLDG	LOCATION / SYSTEM	HAZARDS	CS ?	PRCS ?	ALT - PRCS ?	RECOMMENDATIONS / COMMENTS					
ALL	AIR HANDLERS (Crawl Inside; see Air Handlers Survey below)	Environmental - Noise, Contact With - Electrical, Struck By - Flying Debris	YES	NO	N/A	Eye Protection					
ALL	AIR HANDLERS (Walk-In; see Air Handlers Survey below)	Environmental - Noise, Contact With - Electrical, Struck By - Flying Debris	NO	N/A	N/A	Eye Protection					
113898	ARCHIVES and HISTORY CENTER, ENERGY FACILITY - BACKFLOW PREVENTER PIT	Environmental - Lack of Oxygen, Contact With - Water, Fall to Below = 6.5'	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System					
113898	ARCHIVES and HISTORY CENTER, ENERGY FACILITY - BOILERS (2, MEDIUM)	Environmental - Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door					
100302	BLATT BLDG. - Two manholes to roof drainage system (location: in top level planters along Pendleton St. from the building's main entrance toward Assembly St.)	Environmental - Lack of Oxygen, Contact With - Water, Fall to Below > 10'	YES	YES	Unkown	Not Surveyed. GSD employees not required to enter.					
100302	BLATT BLDG. - Utility tunnel that goes under Pendleton St to Park St / Dept of Transportation	Environmental - Lack of Oxygen, Contact With - Water, Fall to Below > 10'	YES	Until Surveyed Otherwise		Not Sureyed. 1st entry in 2008 using PRCS procedures.					
100303	BROWN BLDG. - BACKFLOW PREVENTER PIT (NW corner near intersection of Pendleton & Sumter Streets)	Environmental - Lack of Oxygen, Contact With - Water, Fall to Below > 10'	YES	YES	YES	Gas Monitor, LOTO, Ladder, Rescue Tripod System					
100303	BROWN BLDG. - Manhole to roof drainage system (location: the most Western top-level planter along Pendleton St.)	Environmental - Lack of Oxygen, Contact With - Water, Fall to Below > 10'	YES	YES	Unkown	Not Surveyed. GSD employees not required to enter.					
110708	COLUMBIA MILLS BLDG, ENERGY FACILITY - BOILERS (2)	Environmental - Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door					
110708	COLUMBIA MILLS BLDG, ENERGY FACILITY - NORTH BACKFLOW PREVENTER PIT	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 5' 4"	YES	YES	YES (ONLY FOR INSPECTION FROM OUTSIDE)	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System					
110708	COLUMBIA MILLS BLDG, ENERGY FACILITY - CENTER BACKFLOW PREVENTER PIT	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 5' 5"	YES	YES	YES (ONLY FOR INSPECTION FROM OUTSIDE)	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System					
110708	COLUMBIA MILLS BLDG, ENERGY FACILITY - SOUTH BACKFLOW PREVENTER PIT	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 4' 8"	YES	YES	YES (ONLY FOR INSPECTION FROM OUTSIDE)	Gas Monitor, LOTO (applied in PRCS), Ladder					
110708	COLUMBIA MILLS BLDG, MAIN ELECTRICAL ROOM - PIT	Contact With - Water, Steam; Fall to Below = 4'	YES	NO	N/A	Gas Monitor, LOTO, Ladder					
ALL	COOLING TOWERS (see Cooling Towers Survey below)	Contact With - Water, Environmental - Bacteria, Molds	YES	NO	N/A	Gas Monitor, Slip Resistant Soled Footwear					
113943	DATA CENTER BLDG - BACKFLOW PREVENTER PIT	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 4' 8"	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder					
113943	DATA CENTER BLDG - FIRE SERVICE PIT	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 4' 8"	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder					
100287	DENNIS BLDG - BACKFLOW PREVENTOR PIT (located at Northwest corner near intersection of Assembly & Senate Streets)	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 35"	YES	YES	CONDITIONAL	Permit not required IF remove entire cover plate prior to entry. Gas Monitor, LOTO (applied in PRCS), Ladder					
100287	DENNIS BLDG - BACKFLOW PREVENTOR PIT (located on North side of stairwell from McEachern Parking Facility; between the Dennis Bldg. & Statehouse)	Environmental - Lack Oxygen, Contact With - Water, Fall to Below = 4' 11"	YES	YES	CONDITIONAL	Permit not required IF remove entire cover plate prior to entry. Gas Monitor, LOTO (applied in PRCS), Ladder					
100287	DENNIS BLDG - CRAWL SPACES BEHIND EACH BATHROOM (16)	Environmental - Lack Oxygen, Electrical; Contact With -Water, Human Waste	YES	NO	N/A	Gas Monitor, LOTO					

CONFINED SPACES SURVEY

Various	ELEVATORS (Shafts/Pits; see Elevators Survey below)	Fall, electrical, hydraulic, water (flood), struck by elevator cab, caught in cables	YES	YES	YES	LOTO prior to entry. Post observer and barriers. Foot protection, gloves. Proper climbing technique.							
100340	ESC DAVID BLDG - BACKFLOW PREVENTER PIT	Environmental - Lack Oxygen, Contact With Water, Fall to Below = 7' 4"	YES	YES	YES (ONLY AFTER LO/TO and OPEN ALL DOORS)	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System							
100347	ESC JOB SERVICE BLDG, 1st FLOOR - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	NO	N/A	N/A	LOTO (Too small to bodily enter)							
100415	FIVE POINTS BLDG - ELEVATOR PITS	Environmental - Electrical, Fall to Below = 13'	YES	NO	N/A	Gas Monitor, LOTO							
113900	FM CUSTODIAL BLDG, BASEMENT - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	NO	N/A	N/A	LOTO (Too small to bodily enter)							
100410	FM ENERGY FACILITY BLDG - BOILERS (2)	Environmental -Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door							
100410	FM ENERGY FACILITY BLDG - DEAERATOR TANK (Basement)	Electrical, Steam, Water, Water Treatment Chemical (CW); Heat; Oxygen Depletion; Noise; Welding; Restricted entry/Exit	YES	YES	NO	Allow tank to cool. Drain and rinse tank. Mechanical ventilation. LOTO. Scaffold and ladder to assist entry. Gas monitor. Hearing protection, gloves, work jump suit. Rescue equipment (wristlets & lanyard). Hot Work Permit, Fire Guard, portable fire extinguisher and PPE for Welding.							
100410	FM ENERGY FACILITY BLDG - TUNNEL (to McEACHERN PARKING FACILITY)	Environmental -Carbon Monoxide (Lack Oxygen); Contact With -Steam, Water; Environmental - Electricity, Heat	YES	YES	YES	Gas Monitor, LOTO; Nextel & Radios only work part way through tunnel requiring an Attendant at each end with a positive communications transfer or the Entrant, if losing reception, exits the tunnel then enters the opposite end of the tunnel to continue work							
104561	GOVERNOR'S MANSION COMPLEX - CALDWELL-BOYLSTON HOUSE, ATTIC	Environmental - Natural Gas, Heat	NO	N/A	N/A	LOTO							
800038	GOVERNOR'S MANSION COMPLEX - FOUNTAIN PIT*	Contact With - Water, Environmental -Gas, Lack Oxygen; Fall to Below = 9'	YES	NO	N/A								
100313	GOVERNOR'S MANSION COMPLEX - LACE HOUSE-ATTIC	Environmental - Gas	NO	N/A	N/A	LOTO							
100314	GOVERNOR'S MANSION, BASEMENT - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	NO	N/A	N/A	LOTO (Too small to bodily enter)							
110713	GRESSETTE-COLLINS BLDG - BACKFLOW PREVENTER PIT	Environmental -Carbon Monoxide (Lack Oxygen), Contact With - Water; Fall to Below = 5' 3"	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System							
100414	HAYNE (DHEC) LABORATORY BLDG - VERTICAL CHASES (24)*	Environmental - Gas, Electrical; Contact With - Water, Lab Wastes; Fall to Below => 50'	*	*	N/A	* Technically, since re-configured, these are no longer Confined Spaces. However, FM Safety Committee procedure was to continue using confined space entry procedures: Gas Monitor, LOTO (must enter shafts to apply); Hard Hat for persons below workers above; Fall Positioning equipment, as required; Open doors for Ventilation. Ladder/Platform system hinders rescue.							
100414	HAYNE (DHEC) LABORATORY BLDG, BASEMENT - BOILERS (2)	Environmental -Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door							
100289	McEACHERN PARKING FACILITY - 2 MANHOLES (SUMP PUMPS)	Environmental - Gas, Contact With -Water, Electrical; Fall to Below > 5'	YES	YES	CONDITIONAL	Gas Monitor, LOTO, PPE. May use Alt-PRCS for top chamber only. PRCS required for entry to bottom chamber and when exit from top chamber is restricted by obstacles such as when replacing a pump.							

CONFINED SPACES SURVEY

110707	MILLS-JARRETT BLDG - BACKFLOW PREVENTER PIT	Environmental -Carbon Monoxide (Lack Oxygen), CW-Water, FB=5'8"	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System							
100342	RUTLEDGE BLDG, PEHNTHOUSE - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used							
100342	RUTLEDGE BLDG, PENTHOUSE - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	NO	N/A	N/A	Only entered when fully shutdown/LOTO and fully opened (rear plate and ports); NO entry made through inspection port							
100411	SENATE ST. BLDG, BASEMENT - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	NO	N/A	N/A	LOTO (Too small to bodily enter)							
100411	SENATE ST. BLDG, SUB-BASEMENT - BOILER	Environmental -Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door							
100333	SIMS-AYCOCK BLDG - BOILERS (2)	Environmental -Carbon Monoxide (Lack Oxygen)	YES	YES	YES	Gas monitor; only enter when fully shutdown/LOTO used; PRCS when enter through Inspection door							
107892	STATE HOUSE (to WADE HAMPTON - TUNNEL (NEW-Rectangular)	Environmental - Lack Oxygen; Contact With Water; Environmental - Electrical	YES	YES	YES	Gas Monitor, LOTO							
107892	STATE HOUSE (to WADE HAMPTON) - TUNNEL (OLD-Oval)	Environmental - Lack Oxygen; Contact With Water, Steam; Environmental - Electrical	YES	YES	YES	Gas Monitor, LOTO							
107892	STATE HOUSE BLDG, UTILITY SPACE (Attic, Level 1 Dome)	Fall to Below = 5' 6"; Contact With - Low ceiling structures	NO	NO	N/A	Bump cap. 2 horizontal chases around dome base for light replacement; each chase has hatch entrance and							
107892	STATE HOUSE BLDG, UTILITY SPACE (UNDER AHU-9)	Fall to Below = > 10' if step through ceiling	YES	NO	N/A	11"x21" entryway, no ladder, no catwalk							
107892	STATE HOUSE BLDG, UTILITY SPACE (UNDER FOUNDATION)	Fall to Below = 5' - 6"; Contact With - Pipes, Ducts; Environmental - Electricity, Steam	YES	NO	N/A	Gas Monitor, LOTO							
100412	STATE LIBRARY BLDG, SUB-BASEMENT	Environmental - Gas; Contact With - Water, Electrical; Fall to Below = 11'	YES	NO	N/A	Gas Monitor, LOTO							
104178	SUMTER ST. BLDG, BASEMENT - PIT	Contact With - Water, Steam; Environmental - Electricity; Fall to Below = 4'	YES	NO	N/A	Gas Monitor, LOTO, Ladder							
100393	SUPREME COURT BLDG - BACKFLOW PREVENTER PIT (SW CORNER)	Environmental - Lack Oxygen; Contact With Water; Fall to Below = 5' 8"	YES	YES	NO	Gas Monitor, LOTO (applied in PRCS), Ladder, Rescue Tripod System							
100300	WADE HAMPTON BLDG - EAST PENTHOUSE VENTILATION PIT	Fall to Below = 9', Electric, Unguarded Fan Motor	YES	YES	NO	Gas Monitor, LOTO (applied inside PRCS), Ladder							
100300	WADE HAMPTON BLDG - WEST PENTHOUSE VENTILATION PIT	Fall to Below = 9', Electric, Unguarded Fan Motor	YES	YES	NO	Gas Monitor, LOTO (applied inside PRCS), Ladder							
100300	WADE HAMPTON BLDG - MECHANICAL ROOM HORIZONTAL PIPE CHASE	Contact With - Asbestos, Steam	YES	YES	YES	Gas Monitor							

CONFINED SPACES SURVEY

AIR HANDLERS - SURVEY 10/96										
BUILDING		TYPE OF FILTER						ENTRY CONFINED SPACE	REMARKS	ENTER
#	NAME	PUSH THROUGH	EXTE RIOR	PULLER	INTERIOR	WINDOW	FLOOR			
3	ROBERT E DAVID- AH-1 MAIN							X		Y
3	ROBERT E DAVID- AH-2 MAIN							X		Y
7	RUTLEDGE- PENTHOUSE AH-MAIN							X	6' x 3' Access door	Y
16	FIVE POINTS- AH-MAIN							X	6' ladder required; filter coil between filter & fans	Y
41	EDGAR A BROWN- AH-MAIN							X	4' x 16" ACCESS DOOR	Y
44	COLUMBIA MILL- B-1, 1-2 & 3, 1-5/6/7, 2- 2/3/4/5, 3-2/3/4/5, 4-2 & 3							X	Remove 1st lower semi-permanent and temporary filters to crawl inside through 2' x 2' x 1' opening	Y
47	HAYNE- BOILER ROOM AH-MAIN							X	4' x 2' Access door; filter coil between filter & fans	Y
47	HAYNE- FRESH AIR MAKEUP-1							X		Y
47	HAYNE- FRESH AIR MAKEUP-2							X		Y
49	AGRICULTURE LAB AH-1							X	6' x 18" ACCESS DOOR	Y
49	AGRICULTURE LAB AH-2							X	6' x 18" ACCESS DOOR	Y
53	SOLOMON BLATT- MAIN AH							X	4' x 2' Access Door; Filter coil between filter and fans	Y
53	SOLOMON BLATT- AH-1 ROOF EAST							X	6' x 18" ACCESS DOOR	Y
53	SOLOMON BLATT- AH-2 ROOF WEST							X	6' x 18" ACCESS DOOR	Y
54	MARION GRESSETTE- AH-MAIN							X	4' x 16" Access door	Y
1	WADE HAMPTON- AH-EAST & WEST			X						N
1	WADE HAMPTON- COMPUTER ROOM AH-1-3			X						N
1	WADE HAMPTON- 1ST-6TH FLOORS FAN COILS			X						N
2	JOHN C CALHOUN- BASEMENT AH-5 & 6			X						N
2	JOHN C CALHOUN- ATTIC AH-1-4				X					N
3	ROBERT E DAVID- 6TH FLOOR COMMISSIONER'S OFFICE CEILING		X						6' Ladder required	N
3	ROBERT E DAVID- CANTEEN CEILING		X						6' Ladder required	N
3	ROBERT E DAVID- COMPUTER ROOM AH-1-5		X							N

CONFINED SPACES SURVEY

4	REMBERT C DENNIS- AH-MAIN EAST		X					6' ladder required	N		
4	REMBERT C DENNIS- AH-MAIN WEST		X						N		
4	REMBERT C DENNIS- 1ST FLOOR AH-1		X						N		
4	REMBERT C DENNIS- 1ST FLOOR AH-2		X						N		
4	REMBERT C DENNIS- COMPUTER ROOM LIEBERT-1		X						N		
4	REMBERT C DENNIS- COMPUTER ROOM LIEBERT-2		X						N		
4	REMBERT C DENNIS- 391 HALL/ROOM UNITS		X						N		
5	GEOLOGY OFFICE- RTU-1-4						X	FLOOR UNITS	N		
6	SC STATE CAPITAL							UNDER RENOVATION THROUGH 9/97	N		
7	RUTLEDGE- COMPUTER ROOM AH-1-8		X						N		
7	RUTLEDGE- AH-ROOM 102				X				N		
7	RUTLEDGE- BASEMENT AH-1-7			X					N		
9	AYCOCK AH-1				X				N		
9	AYCOCK AH-2				X			LOTO (Turn off prior to remove/replace filters)	N		
9	AYCOCK STORAGE ROOM				X				N		
9	AYCOCK ROOM 200A				X				N		
9	AYCOCK 3RD FLOOR FAN COIL		X						N		
9	AYCOCK AH-1-11	X							N		
9	SIMS COMPUTER ROOM AH1-3		X						N		
11	MIDDLETON- 1ST/2ND/3RD FLOOR AHs		X						N		
12	GRESSETTE-COLLINS- AH-1ST/2ND/3RD FLOOR, CEILING		X					8' ladder required	N		
12	GRESSETTE-COLLINS- AH-COMPUTER ROOM		X						N		
12	GRESSETTE-COLLINS- ROOF FRESH AIR MAKEUP			X					N		
13	ASSEMBLY ST PARKING GARAGE								N		
14	SC COMMISSION for the BLIND AH-1-21 ROOFTOP				X				N		
15	FM 925/927 MAIN ST						X		N		
17	GOVERNOR'S MANSION- 1ST/2ND FLOOR BEDROOMS						X		N		
18	GOVERNOR'S MANSION SERVANTS' QUARTERS						X		N		
19	FM FORSYTHE- 1ST FLOOR AH-1 & 2		X						N		
19	FM FORSYTHE- ROOF TOP 1-5				X				N		
20	FM SHOP 921 MAIN ST REAR		X						N		
22	SC DEPT OF ARCHIVES AH-1			X					N		
22	SC DEPT OF ARCHIVES AH-2			X					N		
22	SC DEPT OF ARCHIVES AH-3			X					N		
22	SC DEPT OF ARCHIVES AH-4			X					N		
23	SC STATE LIBRARY- AH-6		X						N		

CONFINED SPACES SURVEY

23	SC STATE LIBRARY- FAN COIL						X			N		
24	SUPREME COURT- AH-1-4				X					N		
24	SUPREME COURT- BASEMENT FAN COILS IN CEILING		X							N		
24	SUPREME COURT- MID-LEVEL FAN COILS		X							N		
25	FM OFFICE 921 MAIN ST- AH-MAIN		X							N		
25	FM OFFICE 921 MAIN ST- BREAK ROOM		X							N		
25	FM OFFICE 921 MAIN ST- HALLWAY CEILING		X							N		
26	FM ENERGY FACILITY- FAN COIL UNITS		X							N		
27	SUMTER ST- AH-1-6		X							N		
32	MIDDLETON- ANNEX 3- AH-1-3		X							N		
32	MIDDLETON- ANNEX 3- AH-MAIN			X						N		
34	GOVERNOR'S MANSION BOYLSTON HOUSE- ATTIC		X						6' ladder required	N		
34	GOVERNOR'S MANSION BOYLSTON HOUSE- GIFT SHOP EQUIPMENT ROOM		X							N		
34	GOVERNOR'S MANSION BOYLSTON HOUSE- 2ND FLOOR		X							N		
35	GOVERNOR'S MANSION LACE HOUSE- AH-1-5				X					N		
36	MIDDLETON UPS- RTU-1			X					Requires personal fall protection equipment	N		
36	MIDDLETON AH-2			X						N		
37	FURMAN E McEACHERN JR PARKING FACILITY- OFFICE		X						6' ladder required	N		
37	FURMAN E McEACHERN JR PARKING FACILITY- CONTROL ROOM		X							N		
39	SIMS/AYCOCK ANNEX- ROOF TOP		X							N		
39	SIMS/AYCOCK ANNEX- 1ST FLOOR		X							N		
39	SIMS/AYCOCK ANNEX- 2ND FLOOR		X							N		
41	EDGAR A BROWN- AH-MULTI-ZONE	X								N		
41	EDGAR A BROWN- ROOM 108 CEILING		X						8' step-ladder required to remove ceiling tile; 10' ladder required to gain access to walkway	N		
41	EDGAR A BROWN- ROOM 347/CANTEEN CEILING				X				6' ladder required	N		
42	SC STATE MUSEUM WORKSHOP- RTUs		X							CONTRACT BILLING	N	
43	STATE SURPLUS PROPERTY OFFICE & WAREHOUSE- RTUs		X							CONTRACT BILLING	N	
44	COLUMBIA MILL- ALL OTHERS (10)				X					WALK-IN ENTRY	N	
46	ADJUTANT GENERAL- AUDITORIUM				X					N		
46	ADJUTANT GENERAL- 1ST FLOOR				X					N		
46	ADJUTANT GENERAL- 2ND FLOOR				X					N		

CONFINED SPACES SURVEY

46	ADJUTANT GENERAL- 3RD FLOOR				X					N		
46	ADJUTANT GENERAL- 1ST FLOOR RADIO ROOM				X					N		
46	ADJUTANT GENERAL- 1ST FLOOR TELEPHONE ROOM CEILING				X					N		
46	ADJUTANT GENERAL- 1ST FLOOR FAN COILS CEILING		X							N		
47	HAYNE- 1ST FLOOR FAN COIL									N		
47	HAYNE- BASEMENT HEATING UNIT									N		
47	HAYNE- ROOFTOP AH-1				X					N		
47	HAYNE- ROOFTOP AH-2				X					N		
47	HAYNE- VENT FAN-5				X					N		
48	MIDDLETON MOTOR GENERATOR		X							N		
49	AGRICULTURE LAB AH-3	X								N		
53	SOLOMON BLATT- ELECTRICAL ROOM		X						6' LADDER REQUIRED	N		
53	SOLOMON BLATT- CANTEEN CEILING		X						6' LADDER REQUIRED	N		
54	MARION GRESSETTE- AH-MULTI-ZONE				X					N		
54	MARION GRESSETTE- 1ST FLOOR SECURITY OFFICE		X						6' LADDER REQUIRED	N		
55	DSS/NORTH TOWER- AH-ALL		X	X						N		
56	MIDDLETON ANNEX 2- AH-1 & 2			X						N		
56	MIDDLETON ANNEX 2- COMPUTER ROOM AH-1-8		X							N		
56	MIDDLETON ANNEX 2- ATTIC		X						Requires extension ladder through ceiling tile; no walkway in attic, must walk beams	N		
57	MIDDLETON ANNEX 1- AH-1,2,3		X						8' step-ladder required then climb from unit to unit	N		
61	DSS/HARDEN ST- ROOFTOP 1			X						N		
61	DSS/HARDEN ST- ROOFTOP 2			X						N		
61	DSS/HARDEN ST- ROOFTOP 3			X						N		
61	DSS/HARDEN ST- 1ST FLOOR LIEBERT		X							N		
64	LAUREL ST WAREHOUSE- RTU-1-8		X							N		
64	LAUREL ST WAREHOUSE- AH-OFFICE CEILING		X							N		
64	LAUREL ST WAREHOUSE- AH-MAIL ROOM CEILING		X							N		
70	SERVICE CENTER (ESC)- AC-1 & 2		X							N		
71	JOB SERVICE (ESC)- RTU 1 & 2			X						N		
73	CENTRAL ADMIN ANNEX (ESC)- ROOFTOP #1	X							6' LADDER REQUIRED	N		
73	CENTRAL ADMIN ANNEX (ESC)- 1ST FLOOR CEILING		X						6' LADDER REQUIRED	N		

CONFINED SPACES SURVEY

73	CENTRAL ADMIN ANNEX (ESC)- 2NDFLOOR CEILING		X					MUST REACH OVER 2ND FLOOR BALCONY GUARDRAILS	N		
73	CENTRAL ADMIN ANNEX (ESC)- 3RDFLOOR CEILING		X					6' LADDER REQUIRED	N		
79	MILLS/JARRETT- RTU-EAST & WEST	X							N		
79	MILLS- AH-1/2/3/4 FLOOR		X						N		
79	JARRETT- 1/2/3/4 FLOOR		X						N		
200	GOVERNOR'S MANSION- POOL HOUSE					X			N		
202	GOVERNOR'S MANSION- LARGE GUARD HOUSE					X			N		
203	GOVERNOR'S MANSION- SMALL GUARD HOUSE					X			N		
204	GOVERNOR'S MANSION- BOMB SHELTER/ STORAGE ROOM					X			N		
205	GOVERNOR'S MANSION CARRIAGE HOUSE- ATTIC 1 & 2		X						N		
206	GOVERNOR'S MANSION- PONY HOUSE					X			N		
207	GOVERNOR'S MANSION- TEA HOUSE					X			N		

CONFINED SPACES SURVEY

BOILER SURVEY 10/96														
BUILDING		BOILER SIZE			CONFINED SPACE		PRCS?		ALT-PRCS?	REMARKS	BOILER TYPE			
#	NAME	SMALL	MED	WALK-IN							FIRE	WATER	OIL	GAS
9	SIMS/AYCOCK- 2ND FLOOR MECHANICAL ROOM		2		YES		YES		YES	3rd boiler is not used	X			
22	SC DEPT OF ARCHIVES- SUB-BASEMENT		1		YES		YES		YES		X			
56	MIDDLETON ANNEX 2- BASEMENT		2		YES		YES		YES					
7	RUTLEDGE - PENTHOUSE	1			NO		NO		NO					
15	FM 925/927 MAIN ST- BASEMENT	1			NO		NO		NO					
17	GOVERNOR'S MANSION	1			NO		NO		NO		X			
26	FM ENERGY FACILITY			2	NO		NO		NO		X			
44	COLUMBIA MILL- ENERGY FACILITY			2	NO		NO		NO		X			
47	HAYNE- BASEMENT MECHANICAL ROOM			2	NO		NO		NO					
71	JOB SERVICE (EMPLOYMENT SECURITY)- 1ST FLOOR	1			NO		NO		NO					

CONFINED SPACES SURVEY

COOLING TOWERS											
LOCATION	# of Towers										
Archives & History Center	2										
Arts Commission	1										
Columbia Mill	2										
David - ESC	1										
Five Points	1										
FM Energy Facility	4										
Gressette-Collins	2										
Harper Administrative Annex - ESC	1										
Hayne DHEC Laboratory	1										
North Towers - DSS	2										
Rutledge	1										
Senate Street OHR	1										
Sims-Aycock	2										
State Library	1										

CONFINED SPACES SURVEY

ELEVATOR SURVEY 11/7/96												
BUILDING #	NAME	PAX	TYPE OF ELEVATOR			SINGLE	TYPE OF PIT/HOISTWAY				REMARKS	
			SVC	FRGHT	DUMB		DOUBLE	TRIPLE	5' or LESS	> 5'		WALK-IN
1	WADE HAMPTON	2	1				1			X		
2	JOHN C CALHOUN	3				3				X		
3	ROBERT E DAVID	4				2	1			X		
4	REMBERT C DENNIS	5				1	2			X		
6	SC STATE CAPITAL											
7	RUTLEDGE	4					2				X	
9	SIMS	3				1	1			X		
9	AYCOCK	2					1			X		
11	MIDDLETON				1	1				X		
12	GRESSETTE-COLLINS	2					1			X		
13	ASSEMBLY ST PARKING GARAGE	1				1				X		
14	SC COMMISSION for the BLIND	2				2				X		
16	FIVE POINTS	2					1				13'	
17	GOVERNOR'S MANSION	1				1				X		NOT IN USE
22	SC DEPT OF ARCHIVES	2				2				X		
23	SC STATE LIBRARY	3				1	1			X		
24	SUPREME COURT	2				2				X		
27	SUMTER ST	1				1				X		
32	MIDDLETON- ANNEX 3	1				1				X		
34	BOYLSTON HOUSE	1				1				X		
35	LACE HOUSE	1				1				X		
41	EDGAR A BROWN	4					2			X		
44	COLUMBIA MILL- TAX COMMISSION	2		1		1	1			X		
44	COLUMBIA MILL- STATE MUSEUM	2		1		3				X		
46	ADJUTANT GENERAL	2					1			X		
47	HAYNE	1		1		1	1			X		
49	AGRICULTURE LAB	1				1				X		
53	SOLOMON BLATT	4					2			X		
54	MARION GRESSETTE	3						1		X		
55	DSS/NORTH TOWER	3						1		X		
61	DSS/HARDEN ST	2					1			X		
73	CENTRAL ADMINI- STRATION ANNEX- EMPLOYMENT SECURITY	2					1			X		
79	MILLS	1				1				X		
79	JARRETT	2					1			X		